

Felger Hart, Inc.
 5049 N State Road 1
 Ossian, IN 46777
 260-597-7202 (O)
 260-597-7204 (F)



Sold To	Work Order Invoice	
Wells County Public Library 200 W. Washington St. Bluffton IN 46714 Att: Sarah MacNeill	Invoice Number:	W18204
Job Location: Wells County Public Library 200 W. Washington St. Bluffton IN 46714	Invoice Date:	Apr 6/22
	Terms:	Net 30
	Customer Code:	10067
	Reference:	
	Customer PO#:	
	Work Order #:	22-08788
	Work Order Type:	Service Call
	Job Location:	Wells County Public Li
	Called By:	Nathanial

Description	Qty	Price	Total
Work Performed			
Temperature gauge is leaking water on pump 3 - 3/4/22			
Checked and found the temperature gauge leaking. Removed the gauge and found the well full of water and the threads broken off inside. Removed, cleaned up the inside of the well and capped the line. Turned the water back on and noted the water line above the gauge shaking badly when the water was turned on. Ordered all material to make the repair and returned. Repiped the water lines as needed and installed the water hammer per Nate's request. Also, installed ball valves to isolate the area for future repairs. System operating properly.			
Labor			
Total Labor			1,000.00
Materials			
Copper Fittings	1.00	59.37	59.37
Fittings	1.00	23.64	23.64
PP Fittings	1.00	181.34	181.34
Water Hammer	1.00	191.33	191.33
Other			
Trip Charge	2.00	35.00	70.00
Equipment			
	Subtotal		1,525.68
	Deposit		0.00
	Total Invoice		1,525.68